

[Headlamp AFS procedure.pdf](#)

Reference	SSM38850
Models	Freelander 2
Title	Freelander 2/LR2 Adaptive Warning Light displayed on dash
Category	Electrical
Last modified	30-Jul-2008 00:00:00
Symptom	201000 Lighting Systems
Content	<p>Issue:</p> <p>Affected VIN range – 086834 to 111504</p> <p>Customer reports an amber flashing headlamp warning light coming on whilst driving.</p> <p>When investigating the fault the Headlamp Control Module (HCM) will show the following DTCs:</p> <p>B1D64-01 - Left Headlamp Swivelling Motor - General Electrical Failure</p> <p>B1D65-01 - Right Headlamp Swivelling Motor - General Electrical Failure</p> <p>This issue only affects cars built within the above VIN range or for cars outside this VIN range but fitted with replacement headlamps between January 2008 and June 2008.</p> <p>Solution:</p> <p>Follow the procedure in the attached document.</p> <p>For any vehicles outside the above VIN range but exhibiting the same DTCs please submit an EPQR with all the information required including stepper motor software details.</p>