

Reference	SSM36525
Models	Freelander 2
Title	Gear Selector cable Squeek (Manual Transmission)
Category	Driveline
Last modified	22-Nov-2007 00:00:00
Symptom	505000 Manual Transmission Concerns
Content	<p>A number reports have been received where the gear selector cables are squeaking, to rectify this concern, please peel the boots back from the cable at the gearbox end, apply a liberal amount of grease around the cable and refit the boots,</p> <p>The grease should conform to specification TSG 3256 or equivalent (Locally sourced)</p>