

Models LF - Freelander 2

Title Freelander 2 / LR2 Body Creak

Last Modified 19-NOV-2008 08:49

Category Body

Symptom 111000 Body Panel(s)/Unibody

Issue: There have been reports of Freelander 2 / LR 2 vehicles exhibiting a Creak noise from the right hand front corner of the vehicle

Cause: This is caused by a touch condition of 2 metal panels within the right hand sill.

Action: If you have a vehicle that has a creak in this area please carry out the actions detailed on the attached Power Point Document.