

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Freelander 2/LR2 (LF)	2011-2015	216517-439912		Vehicles With: AWF21 6-Speed Automatic Transmission
Freelander 2/LR2 (LF)	2011-2015	900000-911855	Halewood	Vehicles With: AWF21 6-Speed Automatic Transmission

---

**MARKETS:**

All except Russia

---

**CONDITION SUMMARY:**
**SITUATION:**

A customer may express a concern about the quality of the automatic gear change.

Examples of this concern are:

- A rough gear change or jerk from stationary when selecting DRIVE (D) from NEUTRAL (N).
- A rough gear change or jerk when releasing the foot brake from a stationary position, whilst vehicle is in DRIVE (D) (handbrake not applied), for example in a traffic jam or pulling away from traffic lights.
- A rough gear change or jerk whilst driving vehicle on coast down from 6th gear (off accelerator), but only when down shifting from 5th to 4th gear.

**This version has been created to change the Causal part number.**

**CAUSE:**

Transmission Control Module (TCM) software programming.

**Suggested Customer Concern Code MN1.**

**ACTION:**

Should a customer express this concern, follow the Diagnostic Procedure below.

---